

in my case the linkage detached from the actuator





Look down to see if the linkage is still attached as it should

A close-up photograph of a mechanical assembly, likely a suspension or steering component. A metal bar is highlighted with a red oval. The text "this is the linkage" is written in red over the bar. The background shows various metal parts, including a blue plastic cap and a circular metal flange.

**this is the
linkage**

**I drilled a hole thru this and secured the assembly.
The actuator link "pin" looks exactly the same as the one
on the link bar in this picture.**

