

VIN	4JGBF2FEXBA749094	Model series/model designation	164.825
Order number		License plate	

Test of compression

Test completed	
Result of test:	
- An rpm difference of 496 rpm was detected.	
- A cylinder leak test must be performed on all cylinders as per the repair instructions.	
Cylinder 1	0 min-1
Cylinder 2	368 min-1
Cylinder 3	496 min-1
Cylinder 4	0 min-1
Cylinder 5	0 min-1
Cylinder 6	0 min-1
Number of cycles	8

Filename: C:\TesterUpdate\Data\mnt\active\DAS\bin\..\trees\pkw\MotorDie\CDI6BIN5EU6\an\ankomp_pub.s

Cell co-ordinate: 9 , 10