



DTB

Date: October 19, 2006
Order No.: P-B-43.10/01
Supersedes:
Group: 43

**SUBJECT: Model 203.061/064/081/084/261/264/281/284/764, Up to Series Production 04/30/2003
Unsatisfactory Power Brake Assistance After a Cold Start**

If you receive customer reports in the above model vehicles of unsatisfactory power brake assistance after a cold start, primarily when maneuvering, this may be the result of low vacuum in the intake manifold. In order to resolve, retrofit an electric brake booster vacuum pump per document SM43.10-P-0003A which is located under "Temporary Postings" in Star TekInfo.



Note: This condition may also be especially prevalent in high altitude regions.



Note: This repair is non-time claimable under Group 43.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.