



Mercedes-Benz

star bulletin**DTB**

Date: 5-24-1996
Order No.: 08/96-1, 08/96-5
Supersedes:
Group: 83

Revision:

**SUBJECT: 08/96-1
RECALLS AND SERVICE CAMPAIGNS: WHEN REPAIRING ANY CAR, ALWAYS
CHECK THE VEHICLE MASTER INQUIRY FOR OPEN CAMPAIGNS**

**08/96-5
MODEL W210
A/C RECEIVER DRIER**

On model 210, reports have been received of uneven cooling / right side air outlet cooler than left side. Check the AC system for correct refrigerant level. If OK, replace the receiver drier. Modified receiver drier introduced in production as of January 1996 with the following chassis numbers: A071317 and J012091. The updated receiver / driver has a new part number 210 830 04 83. Due to production shortages at MBAG, limited stock will only be available at our PDCs within the next few weeks.