

1991 300SL Service Log (Receipts have been kept)

Date	Mileage	Description	Date	Mileage	Description
11-May-01	43575	Purchased from Crown Benz of Dublin Work performed by Crown prior to delivery 45K service Replaced motor mounts Replaced plugs Replaced drive belt Replaced head gasket Flushed brake fluid Replaced coolant Replaced engine front cover gasket Replaced air filter Replaced passenger side visor Replaced instrument cluster Replaced wiper relay Replaced driver door trim Replaced fuel injectors	26-Sep-06	64000	Coolant flush Oil & filter change Brake fluid flush Replaced fuel filter Replaced wiper insert Alignment Replaced air filter
			18-Oct-06	66097	Replaced passenger side head light bulb
			28-Dec-06	66422	Replaced battery
			16-Jun-07	67016	Charged AC
			5-Jul-07		Replaced cabin filter
			8-Aug-07	67107	Oil & filter change Brake fluid flush Replaced fuel hose, check valve Replaced flex brake hoses at all wheels Alignment with new tie rod ends, drag lnk, idler arm bushing
27-Sep-01	47996	Oil & filter change	10-Sep-07	67134	Replaced climate control module Replaced HVAC vacuum distribution module
23-Aug-02	50375	New Michelin Pilots			
11-Sep-02	50632	Replaced battery Brake fluid flush Replaced front rotors and pads Transmission service Rear axle lube	1-Aug-09	70282	Oil & filter change Brake fluid flush Coolant flush Replaced radiator hoses Auto Trans fluid change Replaced thermostat and cap
27-Mar-03	51399	Oil & filter change Replaced fuel filter	8-Aug-10	71213	Replaced driver door window limit switch
26-Apr-03		Replaced right fog light lens	10-Jan-11	73394	Replaced OVP relay
2-Aug-03	52338	Replaced plugs RC12YC			
8-Aug-03	52355	Replaced distributor cap and rotor Replaced hood insulation pad			
28-Aug-03	52830	Converted AC to R134 Oil & filter change			
7-Jul-04	55423	Oil & filter change Brake fluid flush			
1-Apr-05	57492	Oil & filter change			
19-Oct-05	60907	Oil & filter change Brake fluid flush			
23-Jan-06		New floormats			
12-Mar-06	62040	Replaced distributor cap and rotor			
27-May-06	62907	Replaced plugs NGK BKR5E			
27-Jul-06	63065	Replaced ignition coil			