

Effective Serial Number Range

Models	Chassis End Number	
	From	To
215.373	A010123	A029012
215.374	A043422	A045438
215.375	A007963	A045436
215.376	A043426	A045418
215.378	A007971	A027788
215.379	A043461	A045427
220.070	A153298	A300137
220.170	A137766	A452109
220.173	A159266	A301296
220.174	A432175	A452076
220.175	A137746	A452124
220.176	A432934	A452122
220.178	A137763	A301366
220.183	A431158	A452129
220.184	A431168	A452126

Note:

Every vehicle in the VIN range may not be included in the campaign. VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. VMI **always** overrides the bulletin in reference to a specific vehicle's inclusion in a particular campaign. Please also note that Recall and Service Campaigns **do not expire** and may also be performed on a vehicle with a vehicle status indicator.

Affected Instrument cluster part numbers:

A220 540 32 11	A220 540 81 11	A220 540 36 47	A220 540 58 47
A220 540 35 11	A220 540 85 11	A220 540 38 47	A220 540 60 47
A220 540 67 11	A220 540 91 11	A220 540 50 47	A220 540 62 47
A220 540 65 47			

Note:

Only the above part numbers are eligible for replacement.

B. REPLACE INSTRUMENT CLUSTER**Note:**

Prior to starting procedure ensure to:

- Use DAS version 04/06 or later
 - Connect battery charger
 - Follow the order of steps exactly as outlined below
1. Connect Star Diagnosis.
 2. Read data out of old instrument cluster.
 - Navigate through following DAS menus: "Control units/ Information and communication/ ICM – Instrument cluster/ Initial startup/ Initial startup with automatic takeover of previous control unit"
 - Proceed to next step once prompted by DAS to replace control unit

3. Loosen catch of connector (2. Fig. 10.11.1)