

Werkstattinformationssystem Display Document

Sales designation: **ML 430** Vehicle ident. number: **WDB163172*** Engine number: **113.942** Unit number: **27** Entry: Mod Y: Op. no.: **6/ 7**

AD27.19-P-5008A Electronic transmission control (ETC) diagnosis, troubleshooting, fault co... Full-size view Validity OFF Page: **6/ 7**

Code	Message	Priority	Condition	Causes	Remedy
052	impermissible closing of torque converter lockup clutch.	--	engine OM611)		Fault code can be ignored
053	Torque converter lockup clutch is inoperable or has excessive power consumption	P0 140			Fault code can be ignored
055	Target gear is not reached, transmission in mechanical/hydraulic limp-home mode	P0 130	<ul style="list-style-type: none"> Oil level 	<ul style="list-style-type: none"> Wiring harness Oil filter Shift pressure control solenoid valve (Y3/6y2) Control, shift or command valve 	AD27.19-P-5008-01E Inspect oil level in automatic transmission or top up. AR27.00-P-0101A
055	Fault in ETC control module (N15/3), not function critical	--		ETC control module (N15/3)	Replace ETC

i At fault code iSi (background fault), delete fault and only retransmit ETC when