


1833-15720

Test conditions	Observe items 1 to 4
Differential between coldest and warmest outlet temperature	Measured between switching off and switching on of the refrigerant compressor, max. 3 °C
Coldest air outlet temperature from center nozzle	Measures $+ 5 \pm 1$ °C with selector wheel position MIN engaged and function selection 

Conventional tools

1 suction pressure gauge	or assembly tester	1 bar vacuum up to 10 bar gauge pressure
1 high-pressure gauge		0-40 bar gauge pressure
2 Thermometers		-20 °C to +70 °C
1 hygrometer		