

1984 Mercedes 300SD
VIN: WDBCB20A7EA054312
Maintenance & Repair Log

Date	Mileage	Description	Cost	Notes
5/21/09	161495	Replaced turbo drain tube o-rings Replaced valve cover gasket Replace power steering pump Replaced hood pad Oil & filter change	\$ 1,084.82	
6/3/09	162079	Replaced AC pushbutton control Replaced rear window switches Replaced electric antenna	\$ 585.00	Labor only
6/17/09	163091	Replaced coolant reservoir Replaced AC compressor Replaced radiator	\$ 1,406.63	Plus cost of radiator
7/2/09	N/A	Repaired & repadded front & rear seats	\$ 625.00	
7/20/09	163851	Valve adjustment	\$ 266.49	
8/21/09	N/A	Replaced motor mounts Replaced air filter housing mount	\$ 315.00	Labor only
8/24/09	163909	Replace muffler hangers	\$ 63.11	
11/13/09	166109	Oil & filter change Cleaned injectors	\$ 362.14	
12/10/09	166694	Replaced battery	\$ 110.85	
2/3/10	168227	Replaced alternator Replaced coolant hose Replaced steering tie rods, drag link, idler arm	\$ 610.71	
3/11/10	169463	bushings, steering shock Alignment Replaced rear sway bar links Replaced driver's door check strap	\$ 1,313.15	
3/31/10	169955	Oil & filter change	\$ 85.17	
5/24/10	171370	Repaired clock & cleaned instrument cluster	\$ 222.92	
6/7/10	171637	Replaced belts Replaced alternator pulley	\$ 321.82	
7/5/10	173383	Oil & filter change	\$ 85.17	
9/22/10	176198	Oil & filter change Replaced hood release	\$ 98.30	
1/4/11	178970	Oil & filter change Valve adjustment Transmission serviced (changed filter, flushed fluid)	\$ 387.60	
4/27/11	182486	Oil & filter change Replaced rear brake caliper flex hoses Replaced front brakes (pads & rotors) & hub seals	\$ 1,012.56	
6/7/11	183933	Replaced turbo oil supply line gasket & lower seals Replaced exhaust header pipe assembly Repaired exhaust leak	\$ 678.63	

7/8/11	185053	Replaced dashboard assembly Replaced climate control vacuum servos	\$ 1,309.00	Plus cost of dashboard
9/1/11	186247	Oil & filter change Installed knee bolster/panel on left side of dash	\$ 388.99	Plus cost of dash panel
12/21/11	189179	Oil & filter change Replaced front wheel bearings Replaced rear shocks	\$ 1,159.94	
5/9/12	192430	Oil & filter change Replaced front suspension lower ball joints Alignment	\$ 1,091.58	
8/6/12	195231	Oil & filter change	\$ 90.49	
8/7/12	195231	Replaced belts	\$ 170.52	
12/10/12	198263	Oil & filter change Replaced steering linkage dampner	\$ 187.75	
1/15/13	198944	Replaced air filter housing mount	\$ 200.52	
4/19/13	201215	Oil & filter change	\$ 89.13	

TOTAL \$ 14,322.99

Misc. Repairs

Replaced interior b-pillar covers
 Replaced sun visors & visor brackets (parts from 91 560SEL)
 Installed rear headrests (parts from 89 560SEL)
 Replaced interior a-pillar and c-pillar covers
 Replaced rear dome light & reading lights
 Replaced door courtesy lights
 Replaced headlights with w126 2nd generation lights (headlight wipers for appearance only)
 Replaced windshield washer fluid reservoir, pump, spray nozzles & tubing/piping
 Replaced rack dampner bolt
 Replaced fuel primer
 Replaced steering wheel with later air bag model (air bag inoperable)
 Replaced cruise control amp
 Replaced floor mats
 Replaced wood shifter surround
 Replaced front window switches
 Repaired front seat storage nets
 Installed center brake light
 Replaced various interior plastic trim parts
 Replaced all fuses
 Performed diesel purge ever 5,000-7,500 miles
 Replaced air filter every 7,500 miles