

AF83.40-P-6002DA	Temperature difference at center nozzle notably warmer on left than on right.	21.10.96
------------------	---	----------

MODEL 210.### #A as of 002750 up to 071317,  
 210.### #J as of 000633 up to 012091  
 with CODE (580) Air conditioning or Tempmatic for USA  
 with CODE (581) Air conditioning (Automatic)

Damage code	Cause	Remedy:	
83 433 04	Production fault in fluid reservoir (no passage).	Replace fluid reservoir. <input type="checkbox"/> Do <b>not</b> replace AC compressor.	AR83.30-P-6520E

**Parts ordering notes**

Part no.	Designation	Quantity
210 830 03 83	Fluid reservoir (TAU)	1
210 830 04 83	Fluid reservoir (KLA)	1