













- Parts list -










Mode	MD mode	Mod. des. overview	PASSENGER CAR,SEDAN, -N- MODEL YEAR '92 FEDERAL UP TO IDENT NO. WDBGB34E.N A 087222
FIN/MD	140134	Catalog	19F
VIN		Major assembly	
Sales designation	300 SD TURBODIESEL USA; S 350 TURBODIESEL USA	Major assembly MD	
Assortment class	Car	Group	46 - STEERING
Market	North America	Subgroup	120 - STEERING LINKAGE




Item no.	Part number	Designation/description	Quantity	Version
5	A 140 460 06 19	INTERMEDIATE LEVER Replaced by: A 240 460 01 19	-	
5	A 240 460 01 19	INTERMEDIATE LEVER	001	
8	N 900170 008003	SCREW  [046] Up to ident. no.: 12/96	001	
8	N 910105 008014	SCREW  [047] As of ident. no. 01/97	001	
11	A 140 460 08 19	REPAIR KIT INTERMEDIATE LEVER	001	
14	N 000960 014305	SCREW INTERMEDIATE LEVER TO PIVOT BEARING  [046] Up to ident. no.: 12/96	001	
14	N 308765 014021	SCREW INTERMEDIATE LEVER TO PIVOT BEARING  [047] As of ident. no. 01/97	001	
17	N 910113 014001	NUT INTERMEDIATE LEVER TO PIVOT BEARING  [046] Up to ident. no.: 12/96	001	
17	A 202 990 08 51	NUT FOR TAPPING SCREW INTERMEDIATE LEVER TO PIVOT BEARING  [047] As of ident. no. 01/97	001	
20	A 140 330 00 03	TIE ROD	002	
23	A 001 330 62 35	JOINT R.H. THREAD	002	
26	A 001 330 63 35	JOINT L.H. THREAD	002	
29	A 000 338 05 17	CLAMPING PIECE R.H. THREAD	002	
32	A 000 338 06 17	CLAMPING PIECE L.H. THREAD	002	
35	A 140 460 08 05	DRAG LINK	001	
38	A 000 330 12 85	REPAIR KIT TIE ROD BOOT AND DRAG LINK BOOT,RESP.	006	
41	N 913002 012002	NUT DRAG LINK AND TIE ROD TO STEERING ARM  [046] Up to ident. no.: 12/96	006	
41	N 910113 012002	NUT DRAG LINK AND TIE ROD TO STEERING ARM  [047] As of ident. no. 01/97	006	
44	A 140 463 01 32	SHOCK ABSORBER Replaced by: A 140 463 03 32	-	
44	A 140 463 03 32	SHOCK ABSORBER (STEERING SHOCK ABSORBER)	001	
47	N 308676 010023	SCREW STEERING SHOCK ABSORBER TO FRONT AXLE  [046] Up to ident. no.: 12/96	001	
47	N 304017 010033	HEXAGON HEAD BOLT	001	

47	N 304017 010033	HEXAGON HEAD BOLT STEERING SHOCK ABSORBER TO FRONT AXLEM10X40  [047] As of ident. no. 01/97	001
50	N 913004 010010	NUT STEERING SHOCK ABSORBER TO FRONT AXLE  [046] Up to ident. no.: 12/96	001
50	N 910113 010000	NUT STEERING SHOCK ABSORBER TO FRONT AXLE  [047] As of ident. no. 01/97	001
51	A 202 990 10 51	NUT Replaced by: N 910113 012002	-
51	N 910113 012002	NUT DRAG LINK AND TIE ROD TO STEERING ARM	006
53	N 914125 010204	SCREW STEERING SHOCK ABSORBER TO DRAG LINK	001
62	A 140 463 00 90	PROTECTIVE PLATE Replaced by: A 140 463 02 90	-
62	A 140 463 02 90	PROTECTIVE PLATE INTERMEDIATE LEVER	001

- Parts list -

Mode	MD mode	Mod. des. overview	PASSENGER CAR,SEDAN, -N- MODEL YEAR '92 FEDERAL UP TO IDENT NO. WDBGB34E.N A 087222
FIN/MD	140134	Catalog	19F
VIN		Major assembly	
Sales designation	300 SD TURBODIESEL USA; S 350 TURBODIESEL USA	Major assembly MD	
Assortment class	Car	Group	46 - STEERING
Market	North America	Subgroup	120 - STEERING LINKAGE

Item no.	Part number	Designation/description	Quantity	Version
5	A 140 460 06 19	INTERMEDIATE LEVER Replaced by: A 240 460 01 19	-	
5	A 240 460 01 19	INTERMEDIATE LEVER	001	
8	N 900170 008003	SCREW  [046] Up to ident. no.: 12/96	001	
8	N 910105 008014	SCREW  [047] As of ident. no. 01/97	001	
11	A 140 460 08 19	REPAIR KIT INTERMEDIATE LEVER	001	
14	N 000960 014305	SCREW INTERMEDIATE LEVER TO PIVOT BEARING  [046] Up to ident. no.: 12/96	001	
14	N 308765 014021	SCREW INTERMEDIATE LEVER TO PIVOT BEARING  [047] As of ident. no. 01/97	001	
17	N 910113 014001	NUT INTERMEDIATE LEVER TO PIVOT BEARING  [046] Up to ident. no.: 12/96	001	
17	A 202 990 08 51	NUT FOR TAPPING SCREW INTERMEDIATE LEVER TO PIVOT BEARING  [047] As of ident. no. 01/97	001	
20	A 140 330 00 03	TIE ROD	002	
23	A 001 330 62 35	JOINT R.H. THREAD	002	
26	A 001 330 63 35	JOINT L.H. THREAD	002	
29	A 000 338 05 17	CLAMPING PIECE R.H. THREAD	002	
32	A 000 338 06 17	CLAMPING PIECE L.H. THREAD	002	
35	A 140 460 08 05	DRAG LINK	001	
38	A 000 330 12 85	REPAIR KIT TIE ROD BOOT AND DRAG LINK BOOT,RESP.	006	
41	N 913002 012002	NUT DRAG LINK AND TIE ROD TO STEERING ARM  [046] Up to ident. no.: 12/96	006	
41	N 910113 012002	NUT DRAG LINK AND TIE ROD TO STEERING ARM  [047] As of ident. no. 01/97	006	
44	A 140 463 01 32	SHOCK ABSORBER Replaced by: A 140 463 03 32	-	
44	A 140 463 03 32	SHOCK ABSORBER (STEERING SHOCK ABSORBER)	001	
47	N 308676 010023	SCREW STEERING SHOCK ABSORBER TO FRONT AXLE  [046] Up to ident. no.: 12/96	001	
47	N 304017 010033	HEXAGON HEAD BOLT	001	

47	N 304017 010033	HEXAGON HEAD BOLT STEERING SHOCK ABSORBER TO FRONT AXLEM10X40  [047] As of ident. no. 01/97	001
50	N 913004 010010	NUT STEERING SHOCK ABSORBER TO FRONT AXLE  [046] Up to ident. no.: 12/96	001
50	N 910113 010000	NUT STEERING SHOCK ABSORBER TO FRONT AXLE  [047] As of ident. no. 01/97	001
51	A 202 990 10 51	NUT Replaced by: N 910113 012002	-
51	N 910113 012002	NUT DRAG LINK AND TIE ROD TO STEERING ARM	006
53	N 914125 010204	SCREW STEERING SHOCK ABSORBER TO DRAG LINK	001
62	A 140 463 00 90	PROTECTIVE PLATE Replaced by: A 140 463 02 90	-
62	A 140 463 02 90	PROTECTIVE PLATE INTERMEDIATE LEVER	001